

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error or Definition	Errors
1	BRS	L1	402	105/165	USPAT; EPO; JPO; DERWENT	2004/03/02 10:03			0
2	BRS	L2	433	105/168	USPAT; EPO; JPO; DERWENT	2004/03/02 10:04			0
3	BRS	L3	262	105/199.4	USPAT; EPO; JPO; DERWENT	2004/03/02 10:04			0
4	BRS	L4	300	105/167	USPAT; EPO; JPO; DERWENT	2004/03/02 10:04			0
5	BRS	L5	272	105/180	USPAT; EPO; JPO; DERWENT	2004/03/02 10:04			0
6	BRS	L6	148	105/169	USPAT; EPO; JPO; DERWENT	2004/03/02 10:04			0
7	BRS	L7	302	105/199.2	USPAT; EPO; JPO; DERWENT	2004/03/02 10:04			0
8	BRS	L8	77	105/4.4	USPAT; EPO; JPO; DERWENT	2004/03/02 10:04			0
9	BRS	L9	298	280/124.171	USPAT; EPO; JPO; DERWENT	2004/03/02 10:04			0
10	BRS	L10	150	104/298	USPAT; EPO; JPO; DERWENT	2004/03/02 10:05			0
11	BRS	L11	462	104/295	USPAT; EPO; JPO; DERWENT	2004/03/02 10:05			0
12	BRS	L12	755	246/122R	USPAT; EPO; JPO; DERWENT	2004/03/02 10:05			0
13	BRS	L13	103	267/246	USPAT; EPO; JPO; DERWENT	2004/03/02 10:05			0
14	BRS	L14	11001	vehicle same steering same sensor	USPAT; EPO; JPO; DERWENT	2004/03/02 10:06			0
15	BRS	L15	4	vehicle same steering same sensor same secondary same (track or face)	USPAT; EPO; JPO; DERWENT	2004/03/02 10:07			0
16	BRS	L16	27	"scott Phillip".inv.	USPAT; EPO; JPO; DERWENT	2004/03/02 10:08			0
17	BRS	L17	0	"Neale Taylor".inv.	USPAT; EPO; JPO; DERWENT	2004/03/02 10:08			0
18	BRS	L18	27504	Taylor.inv.	USPAT; EPO; JPO; DERWENT	2004/03/02 10:09			0
19	BRS	L19	0	Taylor.inv. same Neale	USPAT; EPO; JPO; DERWENT	2004/03/02 10:09			0